

Ro Óg RunBike - Maintenance:

- Do not leave the Run Bike in damp areas as this will cause damage to the bike.
- Check the overall condition of the of the Run bike regularly to avoid accidents especially with temperature changes or collisions.
- Check all the nuts and bolts, these must always be tight.
- Do not modify the Run bike as this could reduce safety.
- Clean off any dirt on Frame or wheels.
- A specialised waterproof wax finish has been used on the frame. Details of the finish can be obtained by contacting the manufacturer.
- All parts can be replaced. These can be purchased from the manufacturer.



Address:
Liá Fáil, Carhue North,
Riverstick, Co.Cork.
Ireland.

Web:
www.roogltd.com

Tel:
021 477 1983
Mob:
086 8345 867

Email:
roogltd@gmail.com